



Welding diagram

Square tube



Installation plate